
#### UNCLASSIFIED

## AD NUMBER ADB023858 LIMITATION CHANGES TO: Approved for public release; distribution is unlimited. FROM: Distribution authorized to U.S. Gov't. agencies only; Test and Evaluation; 12 AUG 1977. Other requests shall be referred to Electronic Systems Div., Hanscom AFB, MA 01731. AUTHORITY USAFGL ltr 7 Sep 1982

AD B023858


AUTHORITY: USAF62 - Ity, 7 Sep 82





Report No. 131590-611 12 August 1977

ADB 023858



Distribution limited to U. S. Government agencies only; Reason: Test and Evaluation. 12 August 1977. Other requests for this document must be referred to Department of the Air Force, Headquarters Electronic Systems Division (AFSC), Hanscom Air Force Base, Massachusetts 01731, Attention: PPG.

\$12 Aug 77

Prepared for:
Department of the Air Force
Headquarters Electronic Systems Division (AFSC)
Hanscom Air Force Base
Massachusetts 01731

12/11p.

Prepared by: E-Systems, Inc., Montek Division 2268 South 3270 West Salt Lake City, Utah 84119

Contract No. F19628-75-C-0200

CDRL Item A00

DC FILE COPY

YB

408 354

SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered) READ INSTRUCTIONS BEFORE COMPLETING FORM REPORT DOCUMENTATION PAGE 2. GOVT ACCESSION NO. 3. RECIPIENT'S CATALOG NUMBER ESD-TR-77-308 TITLE (and Subtitle) 5. TYPE OF REPORT & PERIOD COVERED Low Temperature Test Report for the AN/TRN-41 TACAN Navigational Set • 6. PERFORMING ORG. REPORT NUMBER 7. AUTHOR(s) B. CONTRACT OR GRANT NUMBER(s) NONE PERFORMING ORGANIZATION NAME AND ADDRESS 10. PROGRAM ELEMENT, PROJECT, TASK E-Systems, Inc., Montek Division 2268 South 3270 West Solt Take City IItah 84110 12. REPORT DATE Electronic Systems Division (AFSC) 12 August 1977 Hanscom AFB, MA 01731 3. NUMBER OF PAGES 4. MONTORING AGENCY NAME & ADDRESS(If different from Controlling Office) 15. SECURITY CLASS. (of this report) Unclassified 15a. DECLASSIFICATION/DOWNGRADING N/A 16. DISTRIBUTION STATEMENT (of this Report) Distribution limited to U.S. Government agencies only; Reason: Test and Evaluation. 12 August 1977. Other requests for this documentmust be referred to Department of the Air Force, Headquarters Electronic Systems Division (AFSC), Hanscom AFB, MA 01731 Attention: DRI 17. DISTRIBUTION STATEMENT (of the obstract entered in Block 20, If different from Report) 719628-45 C-9311 18. SUPPLEMENTARY NOTES 19. KEY WORDS (Continue on reverse side if necessary and identify by block number) AN/TRN-41 TACAN Navigational Set . ABSTRACT (Continue on reverse side if necessary and identify by block number) This report describes the low temperature test as defined in the Equipment Test Plan for Navigational Set, TACAN, AN/TRN-41.

#### LOW TEMPERATURE TEST REPORT

#### for the

#### NÁVIGATIONAL SET, TACAN, AN/TRN-41

This report describes the low temperature test as defined in the Equipment Test Plan for Navigational Set, TACAN, AN/TRN-41, 131500-415.

- 1. Test Identification. Low temperature test as defined in Appendix IV-A (low temperature test procedure) of the Equipment Test Plan for Navigational Set, TACAN, AN/TRN-41.
- 2. Functional Purpose of Test. This test forms a part of the AN/TRN-41 system qualification tests.
- 3. Test Objectives. To demonstrate that the AN/TRN-41 will meet the low temperature requirements of paragraphs 3.2.5.1.1 and 4.2.1.4.3.1 of Specification No. 404L-701-5017A, Part 1 of 2 parts (20 August 1976).
- 4. Description of Test Article. The AN/TRN-41 system consisting of the following was used for the low temperature tests:

Receiver-Transmitter
RT-1201/T
Antenna
AS-3132/T
Antenna Support
AB-1237/T
Filter, DC Power
F-1439/T

Interconnecting Cables


- 5. Summary of Test Results. The AN/TRN-41 showed no functional or physical degradation during the low temperature test.
- 6. Description of Test Facilities and Procedures. The test facilities and test procedures are described in Appendix IV-A of the Equipment Test Plan.
- 7. Test Setup Diagrams. The test setup diagrams are provided in Appendix. IV-A of the Equipment Test-Plan.

- 8. Test Equipment. See Attachment 1 for test equipment used for the low temperature test, pretest, test, and post-test operational tests.
- 9. Test Data. Attachment 2 contains the data sheets for the low temperature test, pretest, test and post-test operational tests and the chamber data sheet.
- 10. Test Conditions. The system was conditioned at -62°C and then operated at -54°C.
- 11. Test Results and Analysis. On the pre-low temperature operational test, the system would occasionally have an RT alarm. This was caused by the number of pulses being detected in the 6 dB Down Detector CCA 1A7 being too low to keep the reply delay monitor circuit happy. This was corrected by changing selectable resistor 1A7R13 to a value (from 180K to 220K) that would allow the reply delay monitor circuit to operate properly.

The system was started in the low temperature test and experienced an RT alarm at -54°C. There was no output power. The problem was caused by a poor solder connection on the output from the VCO CCA 1A9A4 of the synthesizer. This was repaired.

The low temperature test was repeated and no failures occured and no degradation was observed in the visual inspection.

12. Certification. The data sheets shown in Attachment 2 have been signed by a Montek Quality Assurance representative and a DCAS representative, certifying that the test results are authentic, accurate, current and in accordance with the related test plan.



ATTACHMENT 1

TEST EQUIPMENT

#### TEST EQUIPMENT

Description/Manufacturer	Model	Calibration Due Date			
Oscilloscope, Tektronix	465	7/6/77			
Signal Generator, RF, H.P.	612A	6/23/77			
Peak Power Meter, HP	8900B	9/19/77			
Pulse Generator, Data Pulse	110B	5/12/77			
Counter, Fluke	1953	8/12/77			
Half-Ampl. Det. Montek	131500-702	N/A			
RF Detector, Montek	135203-100	N/A			
Monitor Ant., Montek	006300	N/A			
Test Box - Interconnection - Montek	131500-703	N/A			
Power Supply HP	6274B	1/16/78			
Power Supply Acopian		12/9/77			
Power Supply, Sorensen	QR4075A	9/19/77			
Directional Coupler 20 dB, Narda	3042B	N/A			
Directional Coupler 10 dB, Microlab	CBA-78	N/A			
Variable Attenuator, Weinschel 0-10 dB	905	N/A			
RF Attenuator, Weinschel	10 dB	N/A			
Multimeter, Fluke	8120A	8/2/77			
Temperature Chamber, Tenney Engineering	9	0			
Temperature Recorder and Controller	152P15-Pg-295-	111-91 9/9/77			

ATTACHMENT 2
DATA SHEETS

#### APPENDIX IV-K

### DATA SHEET ENVIRONMENTAL TEST

1010	UU-4	13
June	30,	1976

TEST Low Temperature	from 5 May 19//
SYSTEM 002	DATE to 6 May 1977
	ACCEPTABLE X
	NOT ACCEPTABLE
REMARKS The system was subjected to low temperature and the system was subjected to low temperature.	ature tests as outlined by test procedure
131500-415, Appendix IV-A. At the conclusion of	
was reviewed, there was no degradation of performa	ance observed. No discrepancies were
noted during visual inspection.	
DISCREPANCIES	
SIGN OFF INFO	RMATION
ENVIRONMENTAL TEST ENGINEER	DATE
052	
REPRESENTATIVE ENGINEER REDDONAL	DATE S-11-77
QA REPRESENTATIVE In B. hamt	DATE 5-11-77
	VAIL .
	/
DCASD OR AF CONCURRENCE	DATE 5-11-77

June 30, 1976

#### DATA SHEET **OPERATIONAL TESTS**

AN/TRN-41

BEST AVAILABLE COPY

Date 5/5/77

Time /

Tech M

System OOZ

1

Test LOW TEMPERATURE

			3	10		
ora.	Description	Pre-77 Test	5-6-77 Test	Post Test	Requirements	Units
.1	Calibrated RF insertion loss  PL = 32.5 dB	N/A	N/A	N/A	N!/A	N/A
.2	Used in determining RF peak power.  System turn on normal operation	V	~		Check if OK	N/A
.3.1	Anienna radiated signal 15 Hz	~	V		Check if OK	N/A
	135 Hz	<b>ا</b> ـــ			Check if OK	R/A
.3.2	Antenna Speed	66.668	66.662	66,666	65.667±.133	100
.4.1.1	Correct identity code	<u></u>			Check If OK	1./A
.4.1.2	Identity period	37.0	37.0	39.0	37.5 ± 3.75	5 conds
4.2	Peck power (1) Reading of peak power meter Pm = (2) Convert to dBm - 10 log	71mw	66 mw	70mw	N/A	V'elts
	$P_{\rm m} \times 10^3 = P_{\rm m}  dB_{\rm m}$	d3m	\$0,70	50.90	N/A	com
	Total power output in dBm  PmdBm + PL == *Insertion loss see 6.1 above.	d BAI	dBM	dBM	50 dDn	ab
4.3.3	Pulse count	7188	7236	7190	7200 ± 180	Counts
4.4.2	Pulse shape Width (50%) Rise time (10–90%) Fall time (90–10%)	3.4 ms 2.0ms 2.4ms	73.4245 1.8245 2.2245	3,4 ms	3.5 ± 0.5 2 ± 0.25 2.5 ± 0.5	р:: p:: p::
4,4,4	Pulse spacing	i2.ous	12,02	12.02	12.0 ± 0.1	þ:
1,5.2	Delay - 60 ± 10 µs 15 Hz trig to first burst pulse.	/	1—	-	Check if OK	

131500-415

June 30, 1976

# BEST AVAILABLE COPY

#### DATA SHEET OPERATIONAL TESTS AN/TRN-41 (Continued)

8:19 . 9	Description	Test	5-6-77	5-4-77 Post Tost	Requirements	Units	
1.5.3	Correct north Burst - 12 pulse pairs spaced 30 ± 0.1 µs	/	/	MISC	Check if OK		
<b>5.</b> 5	Delay 50 ± 10 µs = 135 Hz trig to first bursh pulse	~	V	~	Check if OK		, ;
4.5.6	Correct Aux buist = 6 pulse pairs spaced 24 ± 0.1 µs	~	~		Check if OK		
1.5.5	RT replies to 3300 interregulations	2600	2663	2714	≥2310 (Cou	nts/Sec	"10 <sup>†</sup> )
.1.6.8	Demand only mode - times to switch from ON to STBY within 70 seconds	1			Check if OK Check if OK		
.1.6.9	Deniard Only mode - time to switch from STB / to ON ST	· -			Check if OK		
, 5 , 10	ON AIR mode	<u></u>			Check if OK		
. , 7.1	DME ONLY mode	<u></u>	~		Check if OK		
/.2	Switch from DME to TACAN	~			Chack if OK		
.3.1	Antenna Alarm - Within four seconds				Check if OK		
8.2	Alarm Resct	~			Check if OK		
. 8.3	RT Alarm - Within five seconds	~			Check if OK		
. 3.4	Alarm Res et	V	1		Check if OK		

AND CLEARED FOR PUBLIC RELEASE

UNDER DOD DIRECTIVE 5200,20 AND

NO RESTRICTIONS ARE IMPOSED UPON

Its use and disclosure.

DISTRIBUTION STATEMENT A

APPROVED FOR PUBLIC RELEASE;
DISTRIBUTION UNLIMITED.